

Instructions for form ASN 7

Annual Notice of Intent to Remove Non-Friable Asbestos-Containing Material

Notification

Oregon asbestos rules require written notification be given to DEQ before you start any asbestos abatement project ([OAR 340-248-0260](#)). Notification must be submitted on DEQ forms and accompanied by the appropriate notification fee if applicable.

Form ASN 7 should be used to notify DEQ of annual non-friable asbestos abatement projects being performed at Schools and Facilities.

Notification deadlines

The Annual Notification does not require a ten-day waiting period in order to start non-friable asbestos removal work.

Who should use Form ASN 7?

Facility owners, Colleges, and School Districts may submit the annual non-friable notification plan for their facilities or schools using [ASN 7](#). Once this form is used, you are required to report removal amounts to DEQ on a quarterly basis, using DEQ [form ASN 3](#).

Contractors doing non-friable asbestos removal for a School, College, or Facility must submit their plan on form ASN 7 and then report their individual projects to DEQ on a quarterly basis, using DEQ form ASN 3.

Other restrictions for non-friable asbestos project under this procedure

Facility owners, Schools, and Colleges may only use Oregon certified asbestos workers on non-friable projects performed using this annual notification procedure.

For non-friable asbestos abatement performed by an Oregon licensed contractor, supply the name of the Competent Person for the non-friable abatement project.

Changes in the project

Any modifications of the annual non-friable asbestos removal plan must be submitted to DEQ for approval separately, using DEQ revision procedures. Modifications must be submitted to DEQ prior to their use.

What are non-friable asbestos removal projects?

- Removal of any amount of non-friable asbestos greater than 3 square or 3 linear feet of material.
- Removal is accomplished according to DEQ guidelines.
- Waste material is taken to a landfill that has a permit to receive demolition waste.

How and where do I file a quarterly report?

Annually notified projects require quarterly reporting. The contractor or facility owner must complete form ASN 3 documenting all work performed during a given calendar quarter. Fax or mail the ASN 3 form to the appropriate DEQ regional office:
Gresham 503-674-5148, Bend 541-388-8283, Medford 541-776-6262, or Salem 503-378-4196.



State of Oregon
Department of
Environmental
Quality

**Air Quality
Asbestos Program**
811 SW 6th Avenue
Portland, OR 97204
Phone: (503) 229-5696
(800) 452-4011
Fax: (503) 229-6762
Contact: Cory Ann Wind
www.oregon.gov/DEQ

*DEQ is a leader in
restoring, maintaining and
enhancing the quality of
Oregon's air, land and
water.*

For more information:
Asbestos Control Section

Gresham
[Susan Patterson](#)
503-667-8414 x55022

Salem
[Dottie Boyd](#)
503-378-5086

Medford
[Steve Croucher](#)
541-776-6107

Coos Bay
[Martin Abts](#)
541-269-2721

Bend
[Frank Messina](#)
541-633-2019

Pendleton
[Tom Hack](#)
541-278-4626

Accessibility information

DEQ is committed to accommodating people with disabilities. Please notify DEQ of any special physical or language accommodations or if you need information in large print, Braille or another format.

To make these arrangements, contact DEQ Communications and Outreach in Portland at 503-229-5696 or call toll-free in Oregon at 800-452-4011; fax to 503-229-6762; or email deqinfo@deq.state.or.us.

People with hearing impairments may call 711.

