

# DEQ's Hazardous Waste Program Annual Hazardous Waste Report Management Method Code Group



State of Oregon  
Department of  
Environmental  
Quality

**Land Quality  
Division  
Hazardous Waste  
Section**

811 SW 6<sup>th</sup> Avenue  
Portland, OR 97204  
Phone: (503) 229-6968  
(800) 452-4011  
Fax: (503) 229-6977  
Contact: Nancy Dollar  
[www.oregon.gov/DEQ/](http://www.oregon.gov/DEQ/)

*Management Method codes describe the type of hazardous waste management system used to treat, recovery, or dispose a hazardous waste. Select the final substantive method used. Review the groups and pick the appropriate code for use on the Generation and Management (GM) forms.*

Code	Reclamation and Recovery
H010	Metals recovery including retorting, smelting, chemical, etc.
H020	Solvents recovery (distillation, extraction, etc.)
H039	Other recovery or reclamation for reuse including acid regeneration, organics recovery, etc. (specify in comments)
H050	Energy recovery at this site - used as fuel (includes on-site fuel blending before energy recovery; report only this code)
H061	Fuel blending prior to energy recovery at another site (waste generated either on site or received from off site)
Destruction or Treatment Prior to Disposal at Another Site	
H040	Incineration - thermal destruction other than use as a fuel (includes any preparation prior to burning)
H071	Chemical reduction with or without precipitation (includes any preparaton or final processes for consolidation of residuals)
H073	Cyanide destruction with or without precipitation (includes any preparation of final processes for consolidation or residuals)
H075	Chemical oxidation (includes any preparation of final processes for consolidation or residuals)
H076	Wet air oxidation (includes any preparation or final processes for consolidation of residuals)
H077	Other chemical precipitation with or without pre-treatment (includes processes for consolidation or residuals)
H081	Biological treatment with or without precipitation (includes any preparaton or final processes for consolidation or residuals)
H082	Adsorption (as the major component of treatment)
H083	Air or steam stripping (as the major component of treatment)
H101	Sludge treatment and/or dewatering (as the major component of treatment; not H071-H075, H077, or H082)
H103	Absorption (as the major component of treatment)
H111	Stabilization or chemical fixation prior to disposal at another site (as the major component of treatment; not H071-H075, H077, or H082)
H112	Macro-encapsulation prior to disposal at another site (as the major component of treatment; not reportable as H071-H075, H077, or H082)
H121	Neutralization only (no other treatment)
H122	Evaporation (as the major component of treatment; not reportable as H071-H083)
H123	Settling or clarification (as the major component of treatment; not reportable as H071-H083)
H124	Phase separation (as the major component of treatment; not reportable as H071-H083)
H129	Other treatment (specify in comments; not reportable as H071-H124))

<b>Disposal</b>	
H131	Land treatment or application (to include any prior treatment and/or stabilization)
H132	Landfill or surface impoundment that will be closed as landfill (to include prior treatment and/or stabilization)
H134	Deepwell or underground injection (with or without treatment; this waste was counted as hazardous waste)
H135	Discharge to sewer/POTW or NPDES ( <b>with prior storage</b> - with or without treatment)
H136	Direct discharge (POTW or NPDES) <b>without prior accumulation or storage</b>
H138	Reinfiltration of treated groundwater
<b>Storage and Transfer</b>	
H141	This site receiving this waste stored/bulked and transferred the waste with no treatment or recovery (H010-H129), fuel blending (H061), or disposal (H131-H135) at that receiving site. This code is for use on the WR Form only. Do not use this code on the Generation & Management (GM) Form. Only used on the Waste Received (WR) form by Treatment, Storage, Disposal (TSD) facilities.